



PTP IEEE1588-2008 accuracy and test

9 lipca 2017 sp9mco

Dodaj komentarz Edytuj

The accuracy of the PTP IEEE1588-2008 on the SAS7210-T MPLS router is shown in figures below.



Depending on the stability of the GM (General Master Clock) , the accuracy of clock recovery by the PTP protocol is 10^{-9} to 10^{-10} .

See more:

<https://sp9mco.wordpress.com/2017/07/09/ptp-ieee1588-2008-accuracy-and-test/>